

1-phase Hybrids-FAQ

Fault code and troubleshooting steps of SHxxRS

Applicable to: SHxxRS series

Abnormal PV1/PV2 current sampling channel (Code 315/316)

Fault name	Abnormal PV1\PV2 current sampling channel (fault code: 315/316)
Fault type	Alarm
Fault condition	Abnormal PV1\PV2 current sampling channel
Steps and methods of troubleshooting	<ol style="list-style-type: none"> 1. Check whether the connection between DC EMI board and power board is reliable. 2. If the fault persists, it is recommended to replace the inverter.

For further information, please download the user manual [here](#).

This manual is intended for professional technicians who are responsible for installation, operation, maintenance and troubleshooting of inverters, and users who need to check inverter parameters. The inverter must only be installed by professional technicians.

The professional technician is required to meet the following requirements:

- Know electronic, electrical wiring and mechanical expertise, and be familiar with electrical and mechanical schematics.
- Have received professional training related to the installation, commissioning and troubleshooting of electrical equipment.
- Be able to quickly respond to hazards or emergencies that occur during installation, commissioning and troubleshooting.
- Be familiar with local standards and relevant safety regulations of electrical systems.
- Read this manual thoroughly and understand the safety instructions related to operations.